

CR NUMBER 25-14062	ACCIDENT DATE 9/27/25	ACCIDENT TIME 1424	DAY OF WEEK SAT	☒ DAYLIGHT ☐ DAWN OR DUSK ☐ DARK	
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) Starbucks Parking Lot 1005 E main St Kent, OH 44240			WEATHER No Adverse		
VEHICLE NO. 1			VEHICLE NO. 2 (OR PROPERTY DAMAGED)		
DRIVER LAST FIRST MIDDLE DOB Roberts Hailey Gabriella 11/23/09			DRIVER LAST FIRST MIDDLE DOB Parked		
ADDRESS 1834 Honeychuck Ln			ADDRESS		
CITY, STATE, ZIP PHONE NUMBER Kent, OH 44240			CITY, STATE, ZIP PHONE NUMBER		
DRIVER'S LICENSE NUMBER STATE (temp permit) OH			DRIVER'S LICENSE NUMBER STATE		
VEHICLE OWNER'S NAME LAST FIRST MIDDLE Roberts Daniel David			VEHICLE OWNER'S NAME LAST FIRST MIDDLE Swisher Nicole Michelle		
ADDRESS Same as driver			ADDRESS 1486 Caminito Padova		
CITY, STATE, ZIP PHONE NUMBER			CITY, STATE, ZIP PHONE NUMBER Chula Vista, CA 91915		
VEHICLE YEAR MAKE MODEL COLOR 2023 Honda Odyssey Blue			VEHICLE YEAR MAKE MODEL COLOR 2022 Subaru Crosstrek Gray		
LICENSE PLATE NUMBER STATE GOW 7610 OH			LICENSE PLATE NUMBER STATE 9BEX183 CA		
INSURANCE COMPANY Farmers			INSURANCE COMPANY Liberty Mutual		
PARTS OF VEHICLE DAMAGED ☐ FRONT ☐ REAR ☐ LEFT ☒ RIGHT 			PARTS OF VEHICLE DAMAGED ☐ FRONT ☐ REAR ☒ LEFT ☐ RIGHT 		
DESCRIBE HOW ACCIDENT OCCURRED Unit 2 was parked and unoccupied in a parking space in the Starbucks parking lot. Unit 1 pulled into the space next to unit 2. The driver of unit 1 advised she hit the gas instead of the brake and struck unit 2. Unit 1 also went forward over a curb and into the grass					
OFFICER / SUPERVISOR SIGNATURE Ofc. [Signature] #251 / Auckland #1238			SKETCH HOW ACCIDENT OCCURRED Starbucks 1005 E main St		INDICATE NORTH BY ARROW Not to Scale 