KENT OHIO POLICE DEPARTMENT

PRIVATE PROPERTY ACCIDENT REPORT

CR NUMBER	ACCIDENT DATE	ACCIDENT TIME	DAY OF WEEK	☒ DAYLIGHT ☐ DAWN OR DUSK ☐ DARK
26-15796	9/12/26	1500 – ≈1530	SAT	

LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION): 5231 Sunnybrook Rd. Kent, OH 44240

WEATHER: U/K


VEHICLE NO. 1	VEHICLE NO. 2 (OR PROPERTY DAMAGED)
DRIVER LAST FIRST MIDDLE DOB: None	DRIVER LAST FIRST MIDDLE DOB: Schonfeld, Barbara Jo. 5/25/52
ADDRESS:	ADDRESS: 5231 Sunnybrook Rd. Apt 320
CITY, STATE, ZIP: PHONE NUMBER:	CITY, STATE, ZIP: Kent, OH. 44240 PHONE NUMBER:
DRIVER'S LICENSE NUMBER: STATE:	DRIVER'S LICENSE NUMBER: STATE: OH
VEHICLE OWNER'S NAME LAST FIRST MIDDLE: Funk, Karla, M.	VEHICLE OWNER'S NAME LAST FIRST MIDDLE: Same
ADDRESS: 5231 Sunnybrook Rd. Apt 105	ADDRESS:
CITY, STATE ZIP: Kent, OH 44240 PHONE NUMBER:	CITY, STATE, ZIP: PHONE NUMBER:
VEHICLE YEAR MAKE MODEL COLOR: 2014 Subu Impreza Blk	VEHICLE YEAR MAKE MODEL COLOR: 2017 NISS Sentra Grey
LICENSE PLATE NUMBER STATE: KQH2783 OH	LICENSE PLATE NUMBER STATE: JBK5558 OH
INSURANCE COMPANY: Progressive: 983576609	INSURANCE COMPANY: Progressive: 870161161
PARTS OF VEHICLE DAMAGED: ☐ FRONT ☒ REAR ☒ LEFT ☐ RIGHT	PARTS OF VEHICLE DAMAGED: ☒ FRONT ☐ REAR ☐ LEFT ☒ RIGHT

DESCRIBE HOW ACCIDENT occurred

Unit #1 was parked facing northound in the parking lot. Unit #2 attempted to pull into the parking spot next to Unit #1. Unit #2 struck Unit #1. Unit #1 was unoccupied. Photos were take of both vehicles. Witness statement collected.

SKETCH HOW ACCIDENT OCCURRED

INDICATE NORTH BY ARROW



Lt J. Nelson #232

OFFICER /SUPERVISOR SIGNATURE

Lt [signature] 232

Revised 7/22/2009