

CR NUMBER 20-2543	ACCIDENT DATE 2-4-20	ACCIDENT TIME 13:46	DAY OF WEEK Tues	<input checked="" type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input type="checkbox"/> DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) Circle K 850 N. Mantua St. Kent, OH 44240			WEATHER No Adverse	
VEHICLE NO. 1		VEHICLE NO. 2 (OR PROPERTY DAMAGED)		
DRIVER LAST FIRST MIDDLE DOB Walker Kyra M 11/10/95	DRIVER LAST FIRST MIDDLE DOB			
ADDRESS 1961 Chippewa Pl.	ADDRESS			
CITY, STATE, ZIP PHONE NUMBER Kent, OH 44240	CITY, STATE, ZIP PHONE NUMBER			
DRIVER'S LICENSE NUMBER STATE TY158982 OH	DRIVER'S LICENSE NUMBER STATE			
VEHICLE OWNER'S NAME LAST FIRST MIDDLE Walker Emerson Joel	VEHICLE OWNER'S NAME LAST FIRST MIDDLE Circle K			
ADDRESS 4192 Amsterdam Rd. SE	ADDRESS 850 N Mantua St.			
CITY, STATE ZIP PHONE NUMBER Scio, OH 43988	CITY, STATE, ZIP PHONE NUMBER Kent, OH 44240 330-696-9049			
VEHICLE YEAR MAKE MODEL COLOR 2005 Chev. Cobalt Red	VEHICLE YEAR MAKE MODEL COLOR			
LICENSE PLATE NUMBER STATE GHL 8497 OH	LICENSE PLATE NUMBER STATE			
INSURANCE COMPANY Statefarm #957-8426 E2835A	INSURANCE COMPANY			
PARTS OF VEHICLE DAMAGED <input checked="" type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT Bumper / Hood	PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT No apparent			
DESCRIBE HOW ACCIDENT OCCURRED Unit 1 began to pull out of a parking spot (north) while at 850 N. Mantua St. (Circle K). Unit 1 stated her breaks stopped working so she pulled forward. Unit 1 was unable to stop and struck the wall of the north side of Circle K. No injuries reported.				
VIDEO SURVEILLANCE FROM CIRCLE K CONFIRMS UNIT 1'S STATEMENT.		SKETCH HOW ACCIDENT OCCURRED		INDICATE NUMBER BY ARROW
				Not to Scale
				J Mantua St
				N
OFFICER / SUPERVISOR SIGNATURE OFC. [Signature] #242				