


CR NUMBER 25-13979	ACCIDENT DATE 9-25-25	ACCIDENT TIME 5:6pm	DAY OF WEEK Thursday	☒ DAYLIGHT ☐ DAWN OR DUSK ☐ DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) 855 Simon Ln Apt 101 Kent, OH 44240				WEATHER clear
VEHICLE NO. 1			VEHICLE NO. 2 (OR PROPERTY DAMAGED)	
DRIVER LAST FIRST MIDDLE DOB unknown			DRIVER LAST FIRST MIDDLE DOB unoccupied	
ADDRESS			ADDRESS	
CITY, STATE, ZIP PHONE NUMBER			CITY, STATE, ZIP PHONE NUMBER	
DRIVER'S LICENSE NUMBER STATE			DRIVER'S LICENSE NUMBER STATE	
VEHICLE OWNER'S NAME LAST FIRST MIDDLE unknown			VEHICLE OWNER'S NAME LAST FIRST MIDDLE Central Window Cleaning	
ADDRESS			ADDRESS 1310 Brookpark Rd	
CITY, STATE ZIP PHONE NUMBER			CITY, STATE, ZIP PHONE NUMBER Cleveland, OH 44109	
VEHICLE YEAR MAKE MODEL COLOR			VEHICLE YEAR MAKE MODEL COLOR 2015 Ford transit Green	
LICENSE PLATE NUMBER STATE			LICENSE PLATE NUMBER STATE PLE6106 Ohio	
INSURANCE COMPANY			INSURANCE COMPANY Encova	
PARTS OF VEHICLE DAMAGED ☐ FRONT ☒ REAR ☐ LEFT ☐ RIGHT			PARTS OF VEHICLE DAMAGED ☐ FRONT ☐ REAR ☐ LEFT ☐ RIGHT	
DESCRIBE HOW ACCIDENT OCCURRED				
Unit 2 was parked + unoccupied in front of 855 Simon Ln. Unit 1 was an EV Amazon truck. Unit 1 was backing up and struck unit 2's ladder that was on top of the vehicle. Unit 2's ladder was damaged + cant be used. There was also broken glass where the accident occurred, possibly the back window of unit 1.				
OFFICER/SUPERVISOR SIGNATURE 			SKETCH HOW ACCIDENT OCCURRED 	

S. Bruno #254, L. Kunka #250