


CR NUMBER 26-12930	ACCIDENT DATE 8/17/26	ACCIDENT TIME 700 - 0723 hrs	DAY OF WEEK Mon.	☒ DAYLIGHT ☐ DAWN OR DUSK ☐ DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) Campus BP Gas Station lot 1434 E. main St. Kent, OH				WEATHER 44240 Cloudy, humid
VEHICLE NO. 1			VEHICLE NO. 2 (OR <u>PROPERTY DAMAGED</u>)	
DRIVER LAST FIRST MIDDLE DOB driverless			DRIVER LAST FIRST MIDDLE DOB	
ADDRESS			ADDRESS	
CITY, STATE, ZIP			CITY, STATE, ZIP	
PHONE NUMBER			PHONE NUMBER	
DRIVER'S LICENSE NUMBER			DRIVER'S LICENSE NUMBER	
STATE			STATE	
VEHICLE OWNER'S NAME LAST FIRST MIDDLE Williams, Michelle Marie			VEHICLE OWNER'S NAME LAST FIRST MIDDLE Campus BP Gas Station	
ADDRESS 11419 Thrush Ave.			ADDRESS 1434 E. main St.	
CITY, STATE, ZIP Cleveland, OH 44111			CITY, STATE, ZIP Kent, OH 44240	
PHONE NUMBER			PHONE NUMBER	
VEHICLE YEAR MAKE MODEL COLOR 2015 Dodge Charger black			VEHICLE YEAR MAKE MODEL COLOR	
LICENSE PLATE NUMBER STATE KER 2876 OH			LICENSE PLATE NUMBER STATE	
INSURANCE COMPANY N/A			INSURANCE COMPANY	
PARTS OF VEHICLE DAMAGED ☐ FRONT ☒ REAR ☐ LEFT ☐ RIGHT rear bumper			PARTS OF VEHICLE DAMAGED ☐ FRONT ☐ REAR ☐ LEFT ☐ RIGHT dented "BP" sign pole	
DESCRIBE HOW ACCIDENT OCCURRED The driver of Unit #1 parked at a gas pump then walked inside the store. Both the clerk and driver watched Unit #1 roll backwards and strike a sign pole. Driver of Unit #1 left the employee his name, phone number and license plate.				
OFFICER / SUPERVISOR SIGNATURE Hillman 237			SKETCH HOW ACCIDENT OCCURRED E. Main St 	
			INDICATE NORTH BY ARROW 	