

CR NUMBER 26-2894	ACCIDENT DATE 02/25/20	ACCIDENT TIME 1538	DAY OF WEEK WED	<input checked="" type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input type="checkbox"/> DARK
-----------------------------	----------------------------------	------------------------------	---------------------------	--

LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) Bent Tree Parking lot 313 N. Water st.	WEATHER Cloudy
---	--------------------------

VEHICLE NO. 1	VEHICLE NO. 2 (OR PROPERTY DAMAGED)
---------------	-------------------------------------

DRIVER LAST FIRST MIDDLE DOB Silvestri Cassandra 9/16/95	DRIVER LAST FIRST MIDDLE DOB Maffei Paige M. 12/13/01
--	---

ADDRESS 3803 Roosevelt Ave. N.E.	ADDRESS 428 Fleeter Ct.
--	-----------------------------------

CITY, STATE, ZIP PHONE NUMBER Canton, OH 44705 (CITY, STATE, ZIP PHONE NUMBER Kent, OH 44240
--	--

DRIVER'S LICENSE NUMBER STATE OH	DRIVER'S LICENSE NUMBER STATE OH
--	--

VEHICLE OWNER'S NAME LAST FIRST MIDDLE Silvestri Anthony	VEHICLE OWNER'S NAME LAST FIRST MIDDLE Maffei Cristo
--	--

ADDRESS SAME	ADDRESS 274 Courtney Rd.
------------------------	------------------------------------

CITY, STATE ZIP PHONE NUMBER SAME	CITY, STATE, ZIP PHONE NUMBER Wexford, PA 15090
---	---

VEHICLE YEAR MAKE MODEL COLOR 2014 Chevy Cruze White	VEHICLE YEAR MAKE MODEL COLOR 2014 Honda Accord Silver
--	--

LICENSE PLATE NUMBER STATE GEU9514 OH	LICENSE PLATE NUMBER STATE MPJ4960 PA
---	---

INSURANCE COMPANY Statefarm	INSURANCE COMPANY Statefarm
---------------------------------------	---------------------------------------

PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input checked="" type="checkbox"/> REAR <input type="checkbox"/> LEFT <input checked="" type="checkbox"/> RIGHT 	PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input checked="" type="checkbox"/> REAR <input type="checkbox"/> LEFT <input checked="" type="checkbox"/> RIGHT
---	---

DESCRIBE HOW ACCIDENT OCCURRED
 Unit #1 and #2 were parked in the lot of 313 N. Waterst.
 Unit #1 and #2 both were backing out of their parking spaces. Unit #2 stopped to avoid striking Unit #1. Unit #1 continued to back up, striking Unit #2 in the rear.

OFFICER/SUPERVISOR SIGNATURE 	SKETCH HOW ACCIDENT OCCURRED Parking lot of 313 N. Waterst.	INDICATE NORTH BY ARROW ↓ "Not to Scale"