CR NUMBER ACCIDENT DATE 11-3-24 TIME C	DAY OF DAYLIGHT DAWN OR DUSK DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) WEATHER Taco Bell - 805 E Main St. Kent, OH 44240 No adverse	
VEHICLE NO.1	VEHICLE NO. 2 (OR PROPERTY DAMAGED)
DRIVER LAST FIRST MIDDLE DOB WESCMANN William Herman 06/2/1204	DRIVER LAST FIRST MIDDLE DOB Rhodes Laci Nichole 05/29/2003
ADDRESS 1771 Notman Rd.	ADDRESS 1174 Princeton St. Apt. Z
CITY, STATE, ZIP PHONE NUMBER Deer Gield, OH 4441	CITY, STATE, ZIP PHONF NI IMPER
DRIVER'S LICENSE NUMBER STATE	DRIVER'S LICENSE NUMBER STATE
VEHICLE OWNER'S NAME LAST FIRST MIDDLE Wesenan William Herman	VEHICLE OWNER'S NAME LAST FIRST MIDDLE Chodes Laci
ADDRESS 1771 Norman Rd.	ADDRESS 4113 Alaska Ave.
CITY, STATE ZIP, OH 44411 PHONE NUMBER	CITY, STATE, ZIP PHONE NUMBER Barberton, OH 44203
VEHICLE YEAR MAKE MODEL COLOR Chevy 2002 Chevillet Cobalt Black	VEHICLE YEAR MAKE MODEL COLOR 2020 HYUNDA; VENUE CITAY
LICENSE PLATE NUMBER STATE S693659 OH	LICENSE PLATE NUMBER STATE KAY5016 0H
INSURANCE COMPANY Progressive 488674358	INSURANCE COMPANY
PARTS OF DEFRONT OF REAR VEHICLE OF THE RIGHT	PARTS OF □ FRONT PREAR LEFT □ RIGHT
DAMAGED DENVEY Rear Fender DESCRIBE HOW ACCIDENT OCCURRED	DAMAGED Driver Rear Fender
Unit Z was waiting in the drive thru line at Taco Bell 805 E Main St.	
Unit I was attempting to reverse and turn around in the taco Bell	
parking lot. While Unit I was reversing, it struck Unit I in the	
driver side rear fender. Both units sustained minor damage	
to the driver side rear funder.	SKETCH HOW ACCIDENT OCCURRED N INDICATE NORTH BY ARROW
	Taco Not to Scale
	13ell UnitZ
	805 E Main
	St. (2)
OFFICER /SUPERVISOR SIGNATURE MATTER 8	Unit