



CR NUMBER 22-12426	ACCIDENT DATE 7/25/22	ACCIDENT TIME 1347	DAY OF WEEK mon	<input checked="" type="checkbox"/> DAYLIGHT <input type="checkbox"/> DAWN OR DUSK <input type="checkbox"/> DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) 1670 Sassafras Ct			WEATHER clear / Sunny	
VEHICLE NO. 1			VEHICLE NO. 2 (OR PROPERTY DAMAGED)	
DRIVER LAST FIRST MIDDLE DOB Smoot James David 2/13/62	DRIVER LAST FIRST MIDDLE DOB Ibrahim Karl John 1/24/02			
ADDRESS 5601 Columbia Dr	ADDRESS 1111 Independence Ave Apt 225			
CITY, STATE, ZIP PHONE NUMBER Bedford Hts, OH 44146	CITY, STATE, ZIP PHONE NUMBER Akron, OH 44310			
DRIVER'S LICENSE NUMBER STATE OH	DRIVER'S LICENSE NUMBER STATE OH			
VEHICLE OWNER'S NAME LAST FIRST MIDDLE CC Mitchell Supply Co. Inc.	VEHICLE OWNER'S NAME LAST FIRST MIDDLE Marques Lucas Rothbarth			
ADDRESS 3001 E Royalton Rd.	ADDRESS 1670 Sassafras Ct Apt 253			
CITY, STATE ZIP PHONE NUMBER Broadview Hts, OH 44147	CITY, STATE, ZIP PHONE NUMBER Kent, OH 44240			
VEHICLE YEAR MAKE MODEL COLOR 2020 Hino white	VEHICLE YEAR MAKE MODEL COLOR 2008 Volkswagen R32 Gray			
LICENSE PLATE NUMBER STATE PKX 2822 OH	LICENSE PLATE NUMBER STATE JTX 7233 OH			
INSURANCE COMPANY Westfield	INSURANCE COMPANY Nationwide			
PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input type="checkbox"/> REAR <input checked="" type="checkbox"/> LEFT <input type="checkbox"/> RIGHT 	PARTS OF VEHICLE DAMAGED <input type="checkbox"/> FRONT <input checked="" type="checkbox"/> REAR <input type="checkbox"/> LEFT <input type="checkbox"/> RIGHT 			
DESCRIBE HOW ACCIDENT OCCURRED				
Unit 1 was making a delivery at Holly Park Apts. Unit 1 was backing up through the parking lot with a loud audible tone. Unit 2 backed into Unit 1 while exiting a parking space in front of 1670 Sassafras Ct. Both-vehicles were damaged and both vehicles were traveling in reverse.				
OFFICER /SUPERVISOR SIGNATURE ofc [Signature] #251				
SKETCH HOW ACCIDENT OCCURRED 