

CR NUMBER 25-13979	ACCIDENT DATE 9-25-25	ACCIDENT TIME 5-6pm	DAY OF WEEK Thursday	☒ DAYLIGHT ☐ DAWN OR DUSK ☐ DARK
LOCATION OF ACCIDENT (STREET NUMBER OR OTHER LOCATION DESCRIPTION) 855 Simon Ln Apt 101 Kent, OH 44240				WEATHER clear

VEHICLE NO. 1 DRIVER LAST FIRST MIDDLE DOB unknown ADDRESS CITY, STATE, ZIP PHONE NUMBER DRIVER'S LICENSE NUMBER STATE VEHICLE OWNER'S NAME LAST FIRST MIDDLE unknown ADDRESS CITY, STATE ZIP PHONE NUMBER VEHICLE YEAR MAKE MODEL COLOR LICENSE PLATE NUMBER STATE INSURANCE COMPANY PARTS OF ☐ FRONT ☒ REAR ☐ LEFT ☐ RIGHT VEHICLE DAMAGED	VEHICLE NO. 2 (OR PROPERTY DAMAGED) DRIVER LAST FIRST MIDDLE DOB unoccupied ADDRESS CITY, STATE, ZIP PHONE NUMBER DRIVER'S LICENSE NUMBER STATE VEHICLE OWNER'S NAME LAST FIRST MIDDLE Central Window Cleaning ADDRESS 1310 Brookpark Rd CITY, STATE, ZIP PHONE NUMBER Cleveland, OH 44109 330-293-1080 VEHICLE YEAR MAKE MODEL COLOR 2015 Ford transit Green LICENSE PLATE NUMBER STATE PLE6106 Ohio INSURANCE COMPANY Encova PARTS OF ☐ FRONT ☐ REAR ☐ LEFT ☐ RIGHT VEHICLE DAMAGED
---	--

DESCRIBE HOW ACCIDENT OCCURRED

Unit 2 was parked + unoccupied in front of 855 Simon Ln. Unit 1 was an EV Amazon truck. Unit 1 was backing up and struck unit 2's ladder that was on top of the vehicle. Unit 2's ladder was damaged + cant be used. There was also broken glass where the accident occurred, possibly the back window of unit 1

SKETCH HOW ACCIDENT OCCURRED

855 Simon Ln Apt.

N

↓

INDICATE NORTH BY ARROW

Not to Scale

OFFICER / SUPERVISOR SIGNATURE

S. Bruno #254, L. Kunka #250